

**SPX****POWER TEAM®**

SPX Corporation  
5885 11th Street  
Rockford, IL 61109-3699 USA

Tech. Services: (800) 477-8326  
Fax: (800) 765-8326  
Order Entry: (800) 541-1418  
Fax: (800) 288-7031

Internet Address:  
<http://www.powerteam.com>



Form No. 100697

Parts List for:

**RH1003**  
**RH1003-FERMI**

## SINGLE-ACTING, SPRING RETURN HYDRAULIC CYLINDER

Max. Capacity: 103.1 Ton at 10,000 PSI



FOR PART NO. RH1003-FERMI ONLY

### **WARNING**

To help avoid personal injury,

- Do NOT disassemble cylinder, the retainer nut is loaded with 300 lbs. spring force.
- All repairs MUST be done by a Power Team authorized Hydraulic Service Center.

---

Sheet No. 1 of 1

---

Rev. Date: 20 Mar. 1991

---

# Parts List, Form No. 100697, Back sheet 1 of 1

Item No.	Part No.	No. Req'd	Description
1	47055	1	Spring Retainer Nut (NOTE: Loaded with 300 lbs. spring force.)
2	308240	1	Plain Insert
3	214499	1	Spring
4	53068	1	Piston
5	*214495	1	"T" Seal with Backup Rings (Smooth side of Backup Ring must be against Seal.)
	†250221	1	"T" Seal with Backup Rings (Smooth side of Backup Ring must be against Seal.)
6	25600	1	Coupler
7	47058	1	Cylinder Standpipe Assembly
8	*214497	1	Rod Wiper
	†250222	1	Rod Wiper
9	*214496	1	"T" Seal with Backup Rings (Smooth side of Backup Ring must be against Seal.)
	†250220	1	"T" Seal with Backup Rings (Smooth side of Backup Ring must be against Seal.)
10	21278-114	1	Relief Valve (Set at 11,500/12,100 PSI; for RH1003-FERMI only)
11	12203	1	Straight Fitting (For RH1003-FERMI only)
12	10623	1	Tee Fitting (For RH1003-FERMI only)
13	†19051	1	O-ring (Viton)
14	†15566	1	Roll Pin
15	†19331	1	Backup Washer

## PARTS INCLUDED BUT NOT SHOWN

*37782	1	Warning Decal
308249	1	Trade Name Decal
†205724	1	Decal (Viton)


Part numbers marked with an asterisk (\*) are contained in Standard Repair Kit No. 300485.

Part numbers marked with a dagger (†) are contained in Viton Seal Kit No. 300585.



## WARNING: To help avoid personal injury,

- Do NOT disassemble cylinder, the retainer nut is loaded with 300 lbs. spring force.
- All repair MUST be done by a Power Team authorized Hydraulic Service Center.



Refer to any operating instructions included with this product for detailed information about operation, testing, disassembly, reassembly, and preventive maintenance.

Items found in this parts list have been carefully tested and selected. **Therefore: Use only genuine replacement parts!**

Additional questions can be directed to our Technical Services Department.